



This couch was adapted for an individual who repeatedly sat on the arm rest of previous couches that invariably broke over time.



A plastic, locked covering was installed in this residence. The individual who lived here repeatedly tinkered with door alarms (pictured above) and thermostats (pictured below).



Below is a picture of an enclosed case used to protect the television.



The picture of the kitchen window below was used in a home for an individual with Prader-Willi Syndrome. The window allowed the individual to see what was happening in the kitchen while limiting the person's ability to have access to the kitchen.



The final picture below is of a simple light fixture that replaced other overhead lights that were often destroyed. This fixture is made mostly of plastic preventing shards of broken glass from flying if someone attempted to break it.

